Page 1 of 4

CAUTION: FAILURE TO INSTALL THIS FIXTURE PROPERLY MAY RESULT IN SERIOUS PERSONAL INJURY OR DEATH AND PROPERTY DAMAGE. We recommend installation by a licensed electrician.

This product must be installed in accordance with applicable installation code(s), by a person familiar with the construction and operation of the product and the hazards involved.*

Caution: Do not exceed maximum wattage noted on fixture. Use only recommended bulbs with fixture.


To Attach Fixture Pipes (Figure 1)

Component Parts

- A Fixture Pipe
- B Fixture Coupling
- 1. Carefully unpack the fixture from the carton.
- 2. Carefully thread fixture pipe (A), threaded end first, over fixture wires.
- 3. Apply a drop of the supplied thread locking compound to the internal threads at the top of the fixture (B) and screw stem into fixture, being careful not to twist the wires.

Note: Application of the thread locking compound is necessary to prevent the stem from loosening during regular maintenance and cleaning of the fixture. Be certain to apply the compound.

4. See instructions below to complete the installation.




(Figure 1)

To Assemble Canopy Pipes to Ceiling Bracket (Figure 2)

Component Parts

- C Hex Nipple (2)
- D Lock Washer (2)
- E Ceiling Bracket
- F Canopy Pipes (2)
- 1. Insert threaded end of hex nipple (C) down through lock washer (D), ceiling bracket (E) and into swivel at the end of canopy pipe (F).
- 2. Tighten securely being sure the notches in the swivels are aligned.

Note: If installing on a sloped ceiling, make certain that the notches in the swivel portion of the stems are oriented toward the lower side of the slope.



(Figure 2)



(continued)

For Steppe Pendant 13-7710

Page 2 of 4

To Complete Fixture Assembly (Figures 3 & 4)

Component Parts


A Fixture Pipe (2) H Plastic Clutch Sleeve (2)

C Hex Nipple I Set Screw (2) F Canopy Pipe (2) J Canopy

G Clutch (2)


Caution: Be sure power is off at the main breaker box prior to installation.

- 1. Thread wires from the fixture pipe (A) through canopy (J). Slide canopy (J) down fixture pipe (A) until it rest on top of fixture.
- 2. Thread the wires from the fixture pipe (A) into and through the canopy pipe (F) up through the hex nipple (C).
- 3. Unscrew the clutch (G) from the canopy pipe (F); slide it across the wires and onto the fixture pipe (A). Follow this with the plastic clutch sleeve (H), oriented so the tapered end of the clutch sleeve nests in the clutch. (Figure 3)




Important: To ensure full connection strength, be sure the tapered end of the plastic clutch sleeve is oriented toward the clutch when assembled. (*Figure 3*).

- 5. Tighten the set screws (I) firmly with hex wrench provided. Only after the set screws (I) are tight should you install to the ceiling.
- 6. Continue with Ceiling Installation below.



(Figure 3)



(Figure 4)



Assembly & Installation Instructions



For Steppe Pendant Fixture 13-7710


Page 3 of 4

To Install to Ceiling (Figures 5)

Component Parts

- E Ceiling Bracket
- I Set Screw (2)
- J Canopy
- L Crossbar
- M Stud (2)

- N Lag Screw (4)
- O Threaded Stud (2)
- P Hex Nut (2)
- Q Barrel Knob (2)
- 1. Thread studs (O) through appropriate holes in crossbar (L) to match holes in canopy (J).
- 2. Using four lag screws (N) attach crossbar (L) to a structural member in the ceiling, centering the crossbar over the outlet box. We've supplied lag screws with your fixture; however, different materials and/or construction methods may require different fasteners. If in doubt, contact a qualified electrician. Do not attach crossbar directly to outlet box.
- 3. Raise fixture to ceiling aligning studs in crossbar (L) with holes in ceiling bracket (E).
- 4. Thread hex nut (P) onto studs (M) and tighten.
- 5. Using suitable wire connectors (not provided) connect fixture wires to supply (white to white and black to black, and bare copper to bare copper or green supply). Push wires back into outlet box.
 - **Caution:** Make sure wire connectors are twisted on securely, and no bare wire is exposed.
- 6. Raise canopy (J) to ceiling over threaded studs (O) and push firmly to ceiling, making sure that no wires are pinched between canopy and ceiling. Fasten with barrel knob (Q). **Note:** Be sure both swivel notches are aligned in the same direction. For sloped ceilings the notches should face towards the down side.
- 7. Refer instructions below and install glass.
- 8. Install light bulbs (not included).
- 9. Restore electricity at main breaker.



(Figure 5)



Assembly & Installation Instructions




For Steppe Pendant Fixture 13-7710

Page 4 of 4

To Install Glass (Figure 6)

Component Parts

- R Large Glass Panels (2)
- S Small Glass Panels (2)
- T Steel Bar
- U Bottom Glass
 - 1. Insert two large glass panels (R) into the slots in the upper tier of the fixture, centering the panels side to side.
 - 2. Insert two small glass panels (S) into the slots in the upper tier of the fixture, centering the panels side to side.
 - 3. Slide bottom glass (U) into slot in bottom tier of fixture, on top of steel bars.
 - 4. Drop steel bar (T) into slots at corners of bottom tier of fixture to secure glass.



If you need further assistance, or find that you are missing any parts, please contact the dealer from which you purchased this product. We hope you enjoy your fixture!

^{*} Hubbardton Forge will not be liable for injury or damage caused by improper installation, lamping or use of this fixture.

